COMPUTER NUMERICAL CONTROL OF MACHINE TOOLS

Laboratory for Manufacturing Systems and Automation Department of Mechanical Engineering and Aeronautics University of Patras, Greece



Dr. Dimitris Mourtzis

Associate professor

Patras, 2017



Chapter 13: Advanced CNC Features



Table of Contents

Chapter 13: Advanced CNC Features	4
13.1 Mirror Imaging	6
13.2 Simple Programs that Employ Mirror Imaging	11
13.3 Polar Rotation	14
13.4 Simple Programs that Employ Polar Rotation	17
13.5 Helical Interpolation	20
13.6 Simple Programs that Employ Helical Interpolation	22
13.7 Summary	27



Objectives of Chapter 13

- Explain the concept of mirror imaging
- **Decide** when the use of **mirror imaging** is appropriate



- Write simple programs in word address that employ mirror imaging
- Explain the concept of polar rotation
- Decide when the use of polar rotation is appropriate
- Write simple programs in word address that **employ polar rotation**
- Write simple programs in word address that employ polar rotation used in a loop



Objectives of Chapter 13

• Explain the concept of helical interpolation

• **Decide** when the use of **helical interpolation** is appropriate

• Write simple programs in word address that **employ helical interpolation**



Mirror Imagining is used to reduce programming time when there is symmetry

- Depending on the quadrant of the mirror imaging some or all of the factors below will be affected :
 - Sign of the axis
 - Milling direction(up- or down- milling)
 - Arc rotation direction (clockwise or counterclockwise)





Figure 1: Mirror Imaging

(source: Σύγχρονες μέθοδοι κατεργασίας υλικών και προγραμματισμός με

Ηλεκτρονικό Υπολογιστή (Η/Υ) ,Δ. Μούρτζης ,κ.α.)





Figure 2: Depending on the quadrant important factors of the machining are affected

(source: Σύγχρονες μέθοδοι κατεργασίας υλικών και προγραμματισμός με Ηλεκτρονικό Υπολογιστή (Η/Υ) ,Δ. Μούρτζης ,κ.α.)



Laboratory for Manufacturing Systems and Automation Associate Professor Dimitris Mourtzis

8/31



Figure 3: Part drawing (Seams W., "Computer Numerical Control, Concepts & Programming")





Figure 4: Tool path for the part shown in Figure 3 (Seams W., "Computer Numerical Control, Concepts & Programming")



%	
O1203	
(* *********)	
(* X0/Y0 = CENTER OF PART)	
(* THIS PROGRAM CALLS SUBPROGRAM	1000)
(* *********)	
N001 G00 G40 G90 G70	(SAFETY LINE)
N10 1G00 X0. Y0. S641 M03	(POSITION OVER PART CENTER)
N102 G45 Z0. H01 M08	(PICK UP LENGTH OFFSET)
N103 M98 P1000 L1	(CALL SUBPROGRAM)
N104 M21	(MIRROR X-AXIS)
N105 M98 P1000 L1	(CALL SUBPROGRAM)
N106 M22	(MIRROR Y-AXIS)
N107 M98 P1000 L1	(CALL SUBPROGRAM)
N108 M23	(TURN OFF AXIS MIRROR)
N109 M22	(MIRROR Y-AXIS)
N110 M98 P1000 L1	(CALL SUBPROGRAM)
N111 G91 G28 Z0. M09	(Z AXIS TO HOME ZERO)
N112 G28 X0. Y0. M05	(X/Y TO HOME ZERO)
N113 M30	(END OF PROGRAM)
01000	
(* ********)	
(* SUBPROGRAM FOR PROGRAM 1203)	
(* *********)	
N001 G81 G90 G99 X1. Y1. Z7 R0. F5.	(DRILL CYCLE - DRILL HOLE 1)
N002 G91 X5 Y5	(DRILL HOLE 2)
N003 X1.	(DRILL HOLE 3)
N004 Y-1.	(DRILL HOLE 4)
N005 X-1.	(DRILL HOLE 5)
N006 G80 G90	(CANCEL DRILL CYCLE)
N007 M99	(RETURN TO MAIN PROGRAM)
%	

Figure 5: Program to machine part in Figure 3

Program N001 Safety line **Explanation** N101 G00X0.Y0. — Positions spindle over the center of the part. S641M03 — Turns on the spindle clockwise at 641 rpm. N102 G45ZO.H01 — Turns on tool length offset using register 1. M08 — Turns on the coolant N103 **M98P1000L1** — Executes subprogram 1000 one time. The part located in the first quadrant will be drilled. N104 M21 — Turns on mirror imaging on the X axis. N105 M98P1000L1 — Executes subprogram 1000 one time. Since the X axis is mirrored, the part in the second quadrant will be drilled. N106 M22 — Turns on mirror imaging on the Y axis. N107 M98P1000L1 — Executes subprogram 1000 one time. Both the X and Y axes are mirrored. Therefore, the part in

the third quadrant will be drilled. **N108**

M23 — Turns off all mirror imaging.

N109

M22 — Turns on the Y axis mirror image. Only the Y axis is now mirrored.

(Seams W., "Computer Numerical Control, Concepts & Programming")



N110 **M98P1000L1** — Executes subprogram 1000 one time. The part in the fourth guadrant will now be drilled. N111 G91G28Z0. — Returns the Z axis to the home zero position. M09—Turns off the coolant. N112 G28X0.Y0. — Returns the X and Y axes to the home zero position. N113 M30 — End of program code. Subprogram Explanation N001 **G81** — Turns on the drill cycle. **G90** — Places the MCU in absolute positioning mode. **G99** — Specifies a return to reference level when the Z axis retracts after each cycle iteration. X1.Y1. — Coordinates of hole #1. **Z-.7** — The final drill depth. **R0.** — Specifies Z0. as the feed engagement point. **F5.** — Sets the drilling feedrate at 5.0 inches per minute. N002 **G91** — Places the MCU in incremental positioning mode. X-.5Y-.5 — Coordinates of hole #2. N003 X1. — Coordinates of hole #3. The MCU is still in incremental mode. N004 X-1. — Coordinate of hole #4. N005 M99 — Returns the MCU to the main program.

Ę

Despite the differences in controllers, there is **certain information** that every MCU needs in order to carry out a **polar rotation**:

- I. The X axis coordinate of the center of rotation
- II. The **Y** axis coordinate of the center of rotation
- III. The index angle, or the angle as measured counterclockwise from the + X axis to the start of the rotation
- IV. The amount of the rotation. Following the initial rotation to the index angle, subsequent rotations may be specified as some angular value other than the index angle. The rotations will occur in a counterclockwise direction
- V. A code to initiate polar rotation
- VI. A code to cancel polar rotation





15/31

Figure 6: Part drawing (Seams W., "Computer Numerical Control, Concepts & Programming")





Figure 7: Polar Rotation (Seams W., "Computer Numerical Control, Concepts & Programming")



%	
O1206	
(* *********)	
(* X0/Y0 = CENTER OF PART)	
(* THIS PROGRAM CALLS SUBPR	OGRAM 2000)
(* *********)	
N001 G00 G40 G90 G70	(SAFETY LINE)
N101 G00 X0. Y0. S3500 M03	(INITIAL MOVE TO CENTER OF PART)
N102 G45 Z0. H01 M08	(PICK UP LENGTH OFFSET)
N103 G61 X0. Y0. A45 D90 L4	(INVOKE POLAR ROTATION)
N104 M98 P2000 L1	(CALL SUBPROGRAM)
N105 G61	(INVOKE POLAR ROTATION)
N106 M98 P2000 L1	(CALL SUBPROGRAM)
N107 G61	(INVOKE POLAR ROTATION)
N108 M98 P2000 L1	(CALL SUBPROGRAM)
N109 G61	(INVOKE POLAR ROTATION)
N110 M98 P2000 L1	(CALL SUBPROGRAM)
N111 G60	(CANCEL POLAR ROTATION)
N112 G00 G91 G28 Z0. M09	(Z AXIS TO HOME ZERO)
N113 G28 X0. Y0. M05	(X/Y TO HOME ZERO)
N114 M30	(END OF PROGRAM)
02000	
(* *********)	
(* SUBPROGRAM FOR PROGRAM	1206)
(* *********)	
N001 G00 X5 Y2.	(POSITION TO THE SLOT)
N002 G01 Z36 F2.8	(FEED TO MILLING DEPTH)
N003 X.5	(MILL SLOT)
N004 G00 Z0.	(RAISE THE SPINDLE)
N005 M99	(RETURN TO MAIN PROGRAM)
%	

Figure 8: Program to machine part in Figure 6

N001 Safely line. N101 G00X0.Y0. — Positions the spindle at the center of the part. S3500M03 —Turns on the spindle clockwise at 3,500 rpm.	Program Explanation	
N102 G4570 H01 Turns on the tool length offset companyation M	09 Turns on the coolant	
N103		
 G61 — Polar relation on code. X0.Y0. — Center point of the rotation. A45 — Starting index angle of rotation. D90 — Amount to rotate coordinate system with each G61 call L4 — Tells the MCU that 4 rotations will occur. N104 		
M98P2000L1 — Jumps to subprogram O2000. N105		
G61 — Causes the next polar rotation to occur. N106		
M98P2000L1 — Jumps to subprogram O2000. N107		
G61 — Causes the next polar rotation to occur. N108		
M98P2000L1 — Jumps to subprogram O2000. N109		
G61 — Causes the next polar rotation to occur.	(Seams W., "Computer Numerical Control, (Concepts & Programming")

18/31

N110 M98P2000L1 — Jumps to subprogram O2000. N111 G60 — Turns off the polar rotation. N112 G00G91G28Z0. — Sends the Z axis to home zero. M09 — Turns oft the coolant. N113 G28X0.Y0. — Sends the X/Y axes to home zero M05 —Turns off the spindle. N114 M30 — End of program code.

Subprogram Explanation N001

G00X-.5Y2. — Positions spindle to the start of the slot.

N002

G01Z-.36F2.8 — Feeds the spindle to milling depth at a feedrate ■ inches per minute.

N003

X.5 — Positions the spindle at feedrate to the end of the slot.

N004

G00Z0. - Retracts the cutter from the slot

N005

M99 – Returns the MCU to the main program



 Helical interpolation is circular interpolation with two axes while simultaneously feeding at a linear rate with the third. The result of this type of operation is a helix



Care must be taken in *calculating the number of turns* and the lead of a helix, be it a thread or other type of part

 Helical interpolation may be used inside of or in conjunction with do loops and subroutines



aboratory for Manufacturing Systems and Automation



Figure 9: Thread milling cutter setup

(Seams W., "Computer Numerical Control, Concepts & Programming")



Laboratory for Manufacturing Systems and Automation Associate Professor Dimitris Mourtzis **Program Format**

G17 – X/Y plane **G18** – X/Z plane **G19** – Y/Z plane

- For the X/Y plane G17 G02/G03 X...Y...I...J...Z...F...
- For the X/Z plane G18 G02/G03 X...Y...I...J...Z...F...
- For the Y/Z plane G19 G02/G03
 X...Y...I...J...Z...F...



Figure 10(a): Part drawing,(b) Program to mill part in Figure 10



N001 Safety line N101	Program Explanation	
G00X1.6Y0. ~ Positions spindle to the start point.		
S800M03 — Turns on spindle clockwise at 800 rpm.		
N102 G457- 818H01 — Rapids spindle to starting depth and turns on the tool length	offset	
M08 — Turns on the coolant	01301.	
N103		
G01X.9694F7 . — Feeds the cutter into the workpiece at 7.0 inches per minute		
N104 G17 Specifies the X/V plane as the circular interpolation plane		
G02 — Initiates circular interpolation clockwise.		
X.9694Y0. — The end coordinates of the circular cut (in this case 360 degrees	s}.	
2918 — The Z coordinate for the helical cut. The Z axis will feed downward to	this coordinate d	uring the circular
X/Y MOTION.		
N105		
G02 — Circular interpolation cods.		
X.9694Y0. — The end coordinates of the circular cut (in this case 360 degrees	5).	
2918 — The Z coordinate for the helical cut. 1-1 10 — The X/X vector from the center of the cutter to the center of the arc		



N106

G02 — Circular interpolation code.

X.9694Y0. — The end coordinates of the circular cut (in this case 360 degrees)

Z-.968 — The Z coordinate for the helical cut.

I-1 JO. — The X/Y vector from the center of the cutter to the center of the ate.

N107

- **G01** Puts the control back in linear interpolation mode.
- **X1.6** Feeds the spindle clear of the part.

N108

G00G91G28Z0.M09 — Sends the spindle to Z home position and turns off the coolant. **N109**

G28X0.Y0.M05 — Sends the spindle to the X/Y home position and turns off the spindle.

N110

M30 — End of program code.

(Seams W., "Computer Numerical Control, Concepts & Programming")



%	
O1211	
N001 G00 G80 G90 G40	(SAFETY LINE)
N101 G00 X.9694 Y0. S2000 M03	(POSITION TO START POINT)
N102 G45 Z.1 H01 M08	(FEED TO START DEPTH)
N103 G17 G02 X.9694 Y0. Z.05 I-1.	J0. F25. (TURN1)
N104 G02 X.9694 Y0. Z.0 I-1. J0.	(TURN 2)
N105 G02 X.9694 Y0. Z05 I-1. J0.	(TURN 3)
N106 G02 X.9694 Y0. Z1 I-1. J0.	(TURN 4)
N107 G02 X.9694 Y0. Z15 I-1. J0.	(TURN 5)
N108 G02 X.9694 Y0. Z2 I-1. J0.	(TURN 6)
N109 G02 X.9694 Y0. Z25 I-1. J0.	(TURN 7)
N110 G02 X.9694 Y0. Z3 I-1. J0.	(TURN 9)
N111 G02 X.9694 Y0. Z35 I-1. J0.	(TURN 10)
N112 G02 X.9694 Y0. Z4 I-1. J0.	(TURN 11)
N113 G02 X.9694 Y0. Z45 I-1. J0.	(TURN 12)
N114 G02 X.9694 Y0. Z5 I-1. J0.	(TURN 13)
N115 G02 X.9694 Y0. Z55 I-1. J0.	(TURN 14)
N116 G02 X.9694 Y0. Z6 I-1. J0.	(TURN 15)
N117 G02 X.9694 Y0. Z65 I-1. J0.	(TURN 16)
N118 G02 X.9694 Y0. Z7 I-1. J0.	(TURN 17)
N119 G02 X.9694 Y0. Z75 I-1. J0.	(TURN 18)
N120 G02 X.9694 Y0. Z8 I-1. J0.	(TURN 19)
N121 G02 X.9694 Y0. Z85 I-1. J0.	(TURN 20)
N122 G02 X.9694 Y0. Z9 I-1. J0.	(TURN 21)

N123 G02 X.9694 Y0. Z95 I-1. J0.	(TURN 22)
N124 G02 X.9694 Y0. Z-1. I-1. J0.	(TURN 23)
N125 G01 X1.6	(FEED OUT OF WORKPIECE)
N126 G00 G91 G28 Z0. M09	(Z AXIS TO HOME ZERO)
N127 G28 X0. Y0. M05	(X/Y AXES TO HOME ZERO)
N128 M30	(END PROGRAM)

Figure 11: Program to mill part in Figure 10



NOO1 Safety line. N1O1	Program Explanation	
G00 X.9694 Y0. — Positions spindle to the start point		
S2000M03 — Turns on spindle clockwise at 2,000 rpm		-
N102		
G45 Z.1 H01 M08 — Rapids spindle to the starting depth (.100 a top of the pa code.	rt) and turns on the	e tool length offset
N103		
317 — Specifies the X/Y plane as the circular interpolation plane. G02 — Initiates circular interpolation clockwise		
2.05 — The Z coordinate for the helical cut	0)	
-1. JO—The X/Y vector from the center of the cutter to the center of the		
525 . — Specifies a feedrate of 25 inches per minute for the motion		
N104 through N124		
Helical motion lines to make turns 2 through 23 of the cutter. Notice the Z axis	feed downward .0	50 inch with each
urn. Since the G17 plane designation command is modal, it is not necessary t	to specify a <mark>G17</mark> w	ith each line. On
nost CNC controls, the circular interpolation codes G02/G03 are also modal a	ind could be omitte	ed as well. Many
programmers, nowever, prefer to specify a G02/G03 at each circular motion to	help clarify the p	orogram's Intent
N125		

G01 X1.6 — Moves the cutter away from the workpiece at feedrate

N126 through N128

Sends the machine to **home zero** and **terminates** the program

(Seams W., "Computer Numerical Control, Concepts & Programming")



Summary 1/2

- Mirror imaging means changing the sign (+ or) of an axis movement
- **Mirror imaging** is used in a program to **save repetitive programming** when the direction of movement is the only difference between part features
- Mirror imaging is normally used in conjunction with subroutines or do loops
- Polar rotation is an indexing of the NC machine's Cartesian coordinate system to some angle other than its normal state
- Polar rotation may be used to perform operations that otherwise would require the use of a rotary axis or lengthy coordinate calculations



Summary 2/2

- Polar rotations may be used in conjunction with do loops or subroutines
- Helical interpolation is circular interpolation with two axes while simultaneously feeding at a linear rate with the third. The result of this type of operation is a helix
- Care must be taken in *calculating the number of turns* and the lead of a helix, be it a thread or other type of part
- Helical interpolation may be used inside of or in conjunction with do loops and subroutines



Vocabulary Introduced in this chapter

- Helical interpolation
- Mirror imaging
- Polar axis system
- Polar rotation
- Tread lead



References

- 1. Chryssolouris G., «Manufacturing Systems: Theory and Practice», 2nd Edition, 2006, Springer-Verlag
- 2. http://www.dptechnology.com/
- 3. Kalpakjian S., «Manufacturing Engineering and Technology», 2nd Edition, 1992, Addison-Wesley Publishing company
- 4. Mattson M., "CNC Programming, Principles and Applications", Delmar, 2002
- 5. Moriwaki T., "Multi-Functional Machine Tool", CIRP Annals Manufacturing Technology, Vol. 57/2, 2008, pp. 736-749
- 6. Seams W., "Computer Numerical Control, Concepts & Programming", 4th Edition, Delmar, 2002
- Γ. Χρυσολούρης, «Συστήματα Παραγωγής Θεωρία και Πράξη» Μέρος Ι και ΙΙ, Εκπαιδευτικές Σημειώσεις, Πανεπιστήμιο Πατρών, 2001,
- 8. Γ. Χρυσολούρης, Δ. Μούρτζης, Κ. Τσίρμπας, Σ. Καραγιάννης, "Ορθογωνική Κοπή", Εκπαιδευτικές Σημειώσεις,
 Πανεπιστήμιο Πατρών, 2000



References

- 9. Γ. Χρυσολούρης, Δ. Μούρτζης, και άλλοι, "Εργαστήρια Μηχανουργικής Τεχνολογίας Ι και ΙΙ"», Εκπαιδευτικές Σημειώσεις για το εργαστήριο του αντιστοίχου μαθήματος, Πανεπιστήμιο Πατρών, 2008 (4η Έκδοση)
- 10. Δ. Μούρτζης, "Αριθμητικός Έλεγχος Εργαλειομηχανών" Εκπαιδευτικές Σημειώσεις, Πανεπιστήμιο Πατρών,2011 (3η Έκδοση)
- Πετρόπουλου Π.Γ., «Μηχανουργική Τεχνολογία ΙΙ. Τεχνολογία κατεργασιών κοπής των μετάλλων», 1998, Εκδόσεις Ζήτη
- Σύγχρονες μέθοδοι κατεργασίας υλικών και προγραμματισμός με Ηλεκτρονικό Υπολογιστή (Η/Υ) ,Δ.
 Μούρτζης ,Κ.Σαλωνίτης

